



Jon Atkinson

Farrier Tools

Calculating Measurements For Surgical Shoes

**3/4 FULLERED
LATERAL EXTENSION STRAIGHT BAR**

Formula

Foot Size (Length + Width + Heel Gap)

+ 1¼" for Toe Bend

+ 1" For Jumping Lateral Branch

EXAMPLE

Foot Length		5¼"	=	5¼"
Foot Width	+	5"	=	10¼"
Heel Gap	+	3"	=	13¼"
Toe Bend	+	1¼"	=	14½"
Lateral Branch				
Jump	+	1"	=	15½"

Total = 15½" 3/4 x 3/8